

# GEOWEB®

## Vegetated Retaining Wall ROADWAY RUNOFF EROSION CONTROL

### VIRGINIA CANYON Clear Creek County Dumont, CO

Tan material forms the front fascia of the near-vertical GEOWEB retaining wall to blend with local soil and arid conditions.



Erosion caused by sheet flow runoff evident on the area not stabilized by the GEOWEB material.



Volunteer vegetation established on the stable embankment.

**PRESTO GEOSYSTEMS®**

Ph: 1-920-738-1328 | [www.prestogeo.com](http://www.prestogeo.com)

© 2019 Presto Geosystems. All Rights Reserved.  
GEOWEB® is a registered trademark of Reynolds  
Presto Products Inc.



**GEOSYSTEMS**